ABC123

Entire Article

2000 Chevrolet Camaro

ARTICLE BEGINNING

GENERAL INFORMATION Exhaust Systems January 2000 Motorist Assurance Program Standards For Automotive Repair

All Makes and Models

CONTENTS

Motorist Assurance Program (MAP)

OVERVIEW OF MOTORIST ASSURANCE PROGRAM
OVERVIEW OF SERVICE REQUIREMENTS AND SUGGESTIONS

Exhaust

CATALYTIC CONVERTERS
EXHAUST AND TAIL PIPES
EXHAUST CONNECTIONS
HANGERS
HEAT RISERS (MECHANICAL EFE DEVICES)
HEAT SHIELDS
MANIFOLDS (CAST AND TUBE TYPE)
MECHANICAL EFE DEVICES
MUFFLERS AND RESONATORS

INTRODUCTION TO MOTORIST ASSURANCE PROGRAM (MAP)

OVERVIEW OF MOTORIST ASSURANCE PROGRAM (MAP)

Automotive industry professionals and interested readers: The Motorist Assurance Program (MAP) is the consumer outreach effort of the Automotive Maintenance and Repair Association, Inc. (AMRA). Participation in the Motorist Assurance Program is drawn from auto repair companies and independents, parts and equipment manufacturers and suppliers, vehicle manufacturers and industry associations.

Our organization's mission is to strengthen the relationship between the consumer and the auto repair industry. We encourage motorists to take greater responsibility for their vehicles-through proper, manufacturer-recommended, maintenance, and endorse participating service and repair shops (including franchisees and dealers) who adopt (1) the MAP Pledge of Assurance to their Customers and (2) the Motorist Assurance Program Standards of Service. All participating service providers have agreed to subscribe to this Pledge and to adhere to the promulgated Standards of Service demonstrating to their customers that they are serious about customer satisfaction.

These Standards of Service require an inspection of the vehicle's (problem) system and that the results be communicated to the customer according to industry standards. Since the industry did not have such standards, the Motorist Assurance Program successfully promulgated industry inspection communication standards in 1994-95 for

ABC123

Entire Article

2000 Chevrolet Camaro

the following systems: Exhaust, Brakes, ABS, Steering and Suspension, Engine Maintenance and Performance, HVAC, and Electrical Systems.

Further, revisions to all of these inspection communication standards are re-published periodically. In addition to the above, standards for Drive Train and Transmissions were promulgated and published in 1998. Participating shops utilize these Uniform Inspection & Communication Standards (UI&CS) as part of the inspection process and for communicating their findings to their customers.

The Motorist Assurance Program continues to work cooperatively and proactively with government agencies and consumer groups toward solutions that both benefit the customer and are mutually acceptable to both regulators and industry. We maintain the belief that industry must retain control over how we conduct our business, and we must be viewed as part of the solution and not part of the problem. Meetings with state and other government officials (and their representatives), concerned with auto repair and/or consumer protection, are conducted. Feedback from these sessions is brought back to the association governing body, and the program adjusted as needed.

To assure recourse for auto repair customers if they are not satisfied with a repair transaction, the Motorist Assurance Program offers mediation and arbitration through the BBB and other similar non-profit organizations. MAP conducted pilot programs in twelve states before announcing the program nationally in October 1998. During the pilots, participating repair shops demonstrated their adherence to the Pledge and Standards and agreed to follow the UI&CS in communicating the results of their inspection to their customers. Complaints and "come-backs" dropped significantly.

To put some "teeth" in the program, an accreditation requirement for shops was initiated. The requirements are stringent, and a self-policing technique has been incorporated which includes the "mystery shopping" of outlets. By year-end 1999, over 4,000 auto repair facilities had been accredited by the Motorist Assurance Program.

We welcome you to join us as we continue our outreach. With your support, both the automotive repair industry and your customers will reap the benefits. Please visit MAP at our Internet site www. motorist.org or contact us at:

1444 | Street, NW - Suite 700 Washington, DC 20005 Phone (202) 712-9042 - Fax (202) 216-9646 E-mail map@bostromdc.org

OVERVIEW OF SERVICE REQUIREMENTS AND SUGGESTIONS

It is MAP policy that all exhaust, brake, steering, suspension, wheel alignment, drive-line, engine performance and maintenance, and heating, ventilation and air conditioning, and electrical services be offered and performed under the standards and procedures specified in these sections.

Before any service is performed on a vehicle, an inspection of the appropriate system must be performed. The results of this inspection must be explained to the customer and documented on an

ABC123

Entire Article

2000 Chevrolet Camaro

inspection form. The condition of the vehicle and its components will indicate what services/part replacements may be "Required" or "Suggested." In addition, suggestions may be made to satisfy the requests expressed by the customer.

When a component is suggested or required to be repaired or replaced, the decision to repair or replace must be made in the customer's best interest, and at his or her choice given the options available.

This section lists the various parts and the conditions that indicate a required or suggested service or part replacement. Although this list is extensive, it is not fully inclusive. In addition to this list, a technician may make a suggestion. However, any suggestions must be based on substantial and informed experience, or the vehicle manufacturer's recommended service interval and must be documented.

Some conditions indicate that service or part replacement is required because the part in question is no longer providing the function for which it is intended, does not meet a vehicle manufacturer's design specification or is missing.

- * Example: An exhaust pipe has corroded severely and has a hole in it through which exhaust gases are leaking.

 Replacement of the exhaust pipe in this case is required due to functional failure.
- * Example: A brake rotor has been worn to the point where it measures less than the vehicle manufacturer's discard specifications. Replacement of the rotor is required because it does not meet design specifications.

Some conditions indicate that a service or part replacement is suggested because the part is close to the end of its useful life or addresses a customer's need, convenience or request. If a customer's vehicle has one of these conditions, the procedure may be only to suggest service.

- * Example: An exhaust pipe is rusted, corroded or weak, but no leaks are present. In this case, the exhaust pipe has not failed. However, there is evidence that the pipe may need replacement in the near future. Replacement of the pipe may be suggested for the customer's convenience in avoiding a future problem.
- * Example: The customer desires improved ride and/or handling, but the vehicle's shocks or struts have not failed. In this case, replacement may be suggested to satisfy the customer's wishes. In this case, replacement of the shocks or struts may not be sold as a requirement.

A customer, of course, has the choice of whether or not a shop will service his or her vehicle. He or she may decide not to follow some of your suggestions. When a repair is required, a MAP shop must refuse partial service on that system if, in the judgment of the service provider, proceeding with the work could create or continue an unsafe condition.

When presenting suggested repairs to the customer, you must

ABC123

Entire Article

2000 Chevrolet Camaro

present the facts, allowing the customer to draw their own conclusions and make an informed decision about how to proceed.

The following reasons may be used for required and suggested services. These codes are shown in the "Code" column of the MAP Uniform Inspection & Communications Standards that follow:

Reasons to Require Repair or Replacement

- A Part no Longer performs intended purpose
- B Part does not meet a design specification (regardless of performance)
- C Part is missing

NOTE:

When a repair is required, the shop must refuse partial service to the system in question, if the repair creates or continues an unsafe condition.

Reasons to Suggest Repair or Replacement

- 1 Part is close to the end of its useful life (just above discard specifications, or weak; failure likely to occur soon, etc.)
- 2 To address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)
- 3 To comply with maintenance recommended by the vehicle's Original Equipment Manufacturer (OEM)
- 4 Technician's recommendation based on substantial and informed experience

NOTE:

Suggested services are always optional. When presenting suggested repairs to the customer, you must present the facts, allowing the customer to draw their own conclusions and make an informed decision about how to proceed.

EXHAUST

SERVICE PROCEDURES REQUIRED AND SUGGESTED FOR PROPER

VEHICLE OPERATION

WARNING: Federal EPA rules prohibit altering an exhaust system in any way that defeats the emission reduction components of a vehicle. Be sure to review and adhere to EPA policy on removing and replacing catalytic converters. Where state or local laws are stricter, they take precedence over these gui del i nes.

NOTE:

Some exhaust systems are of a welded design. It is not required that the entire system be replaced. Determine the need to replace individual components based on conditions of component.

CATALYTIC CONVERTERS

CAUTION: Before working on an exhaust system, review EPA

ABC123 Entire Article

2000 Chevrolet Camaro

regulations on removing and replacing catalytic converters.

Any time a converter has failed, further diagnosis is NOTE:

required to determine the reason(s) for converter failure.

CATALYTIC CONVERTER INSPECTION

Condi ti on Code Procedure

Air injection tube

broken A ... Require repair or replacement of injection tube or

replacement of catalytic converter.

Air injection tube

burnt A ... Require repair or replacement

of injection tube or replacement of catalytic converter.

Air injection tube

leaking A ... Require repair or replacement

of injection tube or replacement of catalytic converter.

Air injection tube

loose A ... Require repair or replacement

of injection tube or replacement of catalytic converter.

Air injection tube

restricted A ... Require repair or replacement of injection tube or replacement of catalytic

converter.

Air injection tube

threads damaged A ... Require repair or replacement

of injection tube or replacement of catalytic

converter.

Air injection tube

threads stripped

(threads missing) A ... Require repair or replacement of injection tube or

replacement of catalytic converter.

Body cracked B .. Require repair or replacement. Converter empty A .. Require repair or replacement.

Converter fill plug

missing C .. Require repair or replacement. Converter missing C Require replacement.

Exhaust gases leaking ... A .. Require repair or replacement. Flanges leaking A ... Require repair or replacement

of flanges.

Inlet pipes cracked B .. Require repair or replacement.

ABC123	Entire Article
	2000 Chevrolet Camaro

<pre>Internal rattle (except pellet-type) 2</pre>		(1) Further inspection required.
Mounting brackets that are part of converter		
broken A Obvious overheating		
Outlet pipes cracked B Pieces of catalyst material found	Requi re	
downstream 1 Plugged A		
Testing has determined that existing converter has been lead-poisoned, contaminated, or failed		y Regarre repraesment.
testing A	Require	repair or replacement.
 If the converter is breat replacement. If an object remove the object. 	0 , 0	
(2) - Overheating is caused by converter. Further diagr	nosis is requi	
the cause of the overhead (3) - Determine cause and corr	•	e that new converter

EXHAUST AND TAIL PIPES

NOTE: For pipes with resonators, also see MUFFLERS AND RESONATORS.

EXHAUST AND TAIL PIPE INSPECTION

Bracket broken	Α	 Require repair or replacement.
Pipe bent out of		
position	В	 Require repair or replacement.
Pi pe broken	Α	 Require repair or replacement.
Pi pe cracked	В	 Require repair or replacement.
Pi pe I eaki ng	Α	 Require replacement.
Pipe missing	С	 Require replacement.
Pi pe pl ugged	Α	 Require replacement.
Pi pe weak due to		
corrosion, but no leaks		
present	1	 Suggest replacement.
		Require repair or replacement.
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

### **EXHAUST CONNECTIONS**

EXHAUST CONNECTION INSPECTION

**ABC123** 

**Entire Article** 

2000 Chevrolet Camaro

AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
Attaching hardware incorrect B Require replacement of
hardware.  Clamp broken A Require replacement.  Clamp loose A . Require repair or replacement.
Clamp missing C Require replacement. Corroded, affecting structural integrity 1 Suggest replacement.
Incorrect type (i.e. flange, ball & socket etc.) B Require replacement.
Leaking       A       Require repair.         Loose       A       Require repair.         AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
HANGERS
HANGER INSPECTION AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
Broken A Require replacement. Corroded, affecting
structural integrity 1 Suggest replacement.  Incorrect type B Require replacement.  Loose A Require repair or replacement.  Missing C Require replacement.  Out of position B Require repair or replacement.  Rubber deteriorated 1 Suggest replacement.  AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
HEAT RISERS (MECHANICAL EFE DEVICES)
HEAT RISER (MECHANICAL EFE DEVICE) INSPECTION ÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄÄ
Broken A Require replacement of affected parts.
Diaphragm inoperative A (1) Require replacement.  Leaking A
Sei zed A Require repair or replacement of affected parts.
Spring broken B Require replacement of spring(s).
Spring inoperative A Require replacement of spring(s).
(1) - If the inoperative diaphragm is separate from the heat

### **ABC123**

### **Entire Article**

2000 Chevrolet Camaro

### **HEAT SHIELDS**

	ÄÄÄ ode	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
Bent Broken Corroded, affecting		Require repair or replacement Require replacement.
structural integrity Loose	A C	Suggest replacement. Require repair or replacement. Require replacement. AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
MANIFOLDS (CAST AND TU	IBE	TYPE)
	E) ÄÄÄ ode	ΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑ
Air injection tube in manifold broken	Α	Require repair or replacement of injection tube or replacement of manifold.
Air injection tube in manifold corroded, affecting structural	1	, and the second
Air injection tube in	ļ	Suggest replacement of injection tube or manifold.
manifold leaking	Α	Require repair or replacement of injection tube or replacement of manifold.
Air injection tube in manifold loose Air injection tube in	Α	Require repair.
manifold restricted	Α	Require replacement of injection tube or manifold.
Air injection tube in manifold threads		•
<u> </u>	А	Require repair of injection tube or manifold.
Air injection tube in manifold threads stripped (threads missing)	А	Require replacement of
Bolt broken		<ul><li>injection tube or manifold.</li><li>Require replacement of bolts.</li><li>Require tightening or replacement of bolts.</li></ul>

ABC123	Entire Article
	2000 Chevrolet Camaro

Bolt missing Corroded, affecting	C Require replacement of bolts.
· · · · · · · · · · · · · · · · · · ·	A Require repair or replacement.
	A Require repair or replacement of cylinder head.
Gasket leaking	3
Heat stove bent	B (1) Require repair or replacement of stove.
Heat stove broken	A (1) Require replacement of stove.
Heat stove corroded,	01 31000.
affecting structural	
	1 (1) Suggest replacement of stove.
Heat stove missing	C (1) Require replacement
· ·	of stove.
Manifold broken	A Require repair or replacement.
Manifold cracked	
Manifold warped	
Out of specification	
Stud broken	
Stud missing	
Stud threads damaged	A Require repair or replacement of stud.
Stud threads stripped	
(threads missing)	A Require replacement of stud.
(1) - Stove may not be avai	ilable separately; this may require
replacement of manifo	old.
ΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑ	ΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑΑ

### MECHANICAL EFE DEVICES

See HEAT RISERS (MECHANICAL EFE DEVICES).

## MUFFLERS AND RESONATORS

MUFFLER AND RESONATOR INSPECTION Condi ti on Code Procedure Body shell distorted, affecting performance or structural integrity ... A ..... Require replacement. Corrosi on hole ...... A ...... Require replacement. Missing ..... C ..... Require replacement. Mounting bracket broken . A .. Require repair or replacement. Mounting bracket cracked ..... B .. Require repair or replacement. Nipple cracked ..... A .. Require repair or replacement. Nipple Loose ..... B ..... Require replacement. Outer wrap peeling

### * EXHAUST SYSTEM UNIFORM INSPECTION GUIDELINES * **ABC123 Entire Article** 2000 Chevrolet Camaro (exhaust not leaking) .. 1 ...... Suggest replacement. Plugged ..... A ...... Require replacement. Puncture (other than a drain hole) ..... A ..... Require replacement. Rattling or knocking noise from inside muffler .... B ...... Require replacement. Seam open (exhaust leaking) ..... A ..... Require replacement. Sound quality unsatisfactory ...... 2 .. Suggest replacement to address customer need and/or request. Split (exhaust leaking) . A ..... Require replacement. Weak due to corrosion, but no leaks present ...... 1 ....... Suggest replacement.

# **END OF ARTICLE**