

Stop drill these locations minimum
(Carefully inspect and drill as required everywhere else)

