

OHMS	Gauge Reads	
90	1.000	F
76	0.875	7/8
64	0.750	3/4
53	0.625	5/8
45	0.500	1/2
37	0.375	3/8
29	0.250	1/4
18	0.125	1/8
0	0.000	E

