


SYMBOL CHART

- MULTIPLE CONNECTOR
- TERMINAL JUNCTION
- LINE FUSE
- CIRCUIT BREAKER
- BATTERY
- FULL LINES INDICATE STD. WIRING
BROKEN LINES INDICATE R.P.O. WIRING



Electrical Circuit Diagram—Series 1000 Thru 3500 With Turn Signals

TM-6751-1